From: Serviceteam RB <ServiceteamRB@brandweeraa.nl>
Date: Tue, 28 Jun 2022 at 11:33
Subject: FW: Bedankt voor je vraag
To: [redacted]@gmail.com <[redacted]@gmail.com>
Cc: <ServiceteamR[redacted]l>

Hello [redacted],

The restaurant has to meet the requirements of the Dutch Buildingcode (Bouwbesluit 2012).
That means the restaurant has to be fireresistant from your appartment for minimal 30 minutes.
At this point there is no fireprotection between the restaurant and the appartments because the ventilation shaft forms an open connection through wich smoke and fire can very quickly spread forming a danger to you as resident of the appartments.
It is not allowed to connect the ventilation of the restaurant to the ventilationshaft of the appartments.
However it is the responsibility of the restaurant owner to make the situation right and to meet the requirements of the building code.
The Fire Service of Amsterdam has no authority for legal action, that is the City of Amsterdam.

We hope we have informed you enough,

Kind regards

Vriendelijke groet,

[redacted]viceteam medewerker
020 555 6000 | aanwezig op ma, di, wo en do

BRANDWEER
Amsterdam-Amstelland

Brandweer Amsterdam-Amstelland
Kazerne Nico | IJ-tunnel 4 | 1011 TA | Amsterdam
www.brandweeraa.nl