From: "5.1.2,e" <5.1.2,e>
Sent: Thu, 24 Nov 2022 19:22:48 +0200
To: "Project Koninginneweg" <5.1.2,i@amsterdam.nl>
Cc: "5.1.2,e" <5.1.2,e@gmail.com>; "5.1.2,e" <5.1.2,e>
Subject: Mould in the household and other issues
Attachments: mould kw 5.1.2,e.pdf

Dear 5.1.2,e

we were told by the KBG that we should report issues with water and humidity in the basement which is likely to be caused by the construction work on the KW. I attach my presentation - we have serious mould issues for the 1st time ever in the basement since we moved in 6 years ago, for a couple of months now.

More points of concern:

In previous mails I have kindly asked you to start a conversation with the GVB to stop – in future - the tram ringing when it enters a tram stop and when it leaves it. As one of the houses with the future tram stop in front of the house and being on the ground floor, we will be most adversely affected by this. It will basically make our lives hell if there is ringing every 6 minutes (2x), Busses do not need to do this, so why do the trams do it? It is more like a bad habit tram drivers seem to have gotten into. Especially in front of residential houses but also for the people working at Wessels the groente shop this is going to be a nightmare. Can you react to this please, I have written to you before on this.

My 3rd issue is the design of the street. It seems you have more or less built the same street, at least were we live (KW 5.1.2,e. You made the bicycle path so wide that, like before, when there is a traffic jam caused by the tram (which tries to go straight to Amstelveenseweg), cars will very likely bypass on the bicycle lanes to get to "their" lane on teh right far too early on, ie before Saxen Weimarlaan, again endangering the cyclists. Is there no learning or listening (since we have repeated this many times) from the Gemeente? What are you planning to do to make sure this cannot happen and the cyclists are protected?

Kind regards
5.1.2,e

5.1.2,e
Koninginneweg 5.1.2,e
5.1.2,e Amsterdam
Netherlands
5.1.2,e