Mould in the basement




Nov. 2022

Basement room, street side (in the back, there is a kruipruimte of ca. 1m depth)



streetside



Wardrobe with sliding doors on the other side of the room, behind this the wall to the kruipruimte

Ca. middle of october, we discovered mould on may items in the wardrobe (see next slide). In 6 years, we have never had mould!

Mould in the wardrobe, 2 examples

Mould on a boots





Mould on a lampshade

Basement bathroom, backside of street room (under the stairs)



Shower with wall to kruipruimte



For 3 months, we put this rehgips plate in the shower (without using the shower), it was full of mould